


GLF - OP017 Option Servo Saver Assembly Guide

Sep-2020



P1, Crank 1	x1	P7, 3x4.5x0.1 Shim	x5
P2, Crank 2	x1	P8, Servo Horn	x1
P3, Saver Spring	x1	P9, M1.5x4 TM	x1
P4, Spring Cap	x1	P10, M2x4 KM	x2
P5, BE-3625	x2	P11, M2x4 TM	x1
P6, Saver Stand	x1	P12, 257020	x1
		P13, 307520	x1



P12

P13

Note: This ball joint are improved (since it is too weak) and strong enough not easy broken once hit the track. Highly recommend to replace it on steering link.
P12 fit for BS-2502
P13 fit for BS-3025

